


2/13/2017 1:41:00 PM

Vehicle Suzuki GSXR750 Year 2006

Coil On Plug -
Cylinder 4 has fouled Sparkplug
COP - Cyl 3 15 Pin ECU